

Inspection Report


Report No.: XYSL-130530
Supplier : XY-GLOBAL

Inspection Date: 28th Jun, 2013
Inspector: Leo

Inspection only for:	<u>Inspection Result:</u>
PO : XYSL-130530 Item No. XY11SL020	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL020	22000PCS	5% inspection	0pcs	No failure	22000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. The test report

[illegible]