

Inspection Report

Report No.: XYSS-130904
Supplier : XY-GLOBAL

Inspection Date: 11th Oct-, 2013
Inspector: LEO

Inspection only for: PO . XYSS-130904 Item No. Samples of aluminum alloy part	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Samples of aluminum alloy part	6PCS	100% inspection	0	No failure	6pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Packing
	
3. Product:	4. Product:
	
5. Product :	6. Product:

	CNC CNC CNC CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316POM
	&NBSP;
	CNC CNC
	gague
MOQ	
/	+/- 0.01
	T / T 5050T / T
	CNC CNC CNC CNC ·
	CNC
	20-25&NBSP;T / T 50
	CNC
1.Name OEM CNC	
2.Process CNC	
3. AL6061 AL6065AL6063AL7075POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6 100	
7.Specification OEM	
8 25-30	
9 CNC accessoried	
10 AustrialEU	
11&NBSP; ISO 9001	
ISO 110	
2	
3 sureface finishment kindls abailable	
4	
5	
6	
7	
CNC &NBSP;	
CNC	
CNC ISO9001	
CNC	
CNC OEM	