

Inspection Report

Report No.: XYK-140506
Supplier : XY-GLOBAL

Inspection Date: 4th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYK-140506 Item No.XY-142069	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-142069	39000PCS	1% inspection	0pcs	No failure	39000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

6. Report:

	OEM
ADC12A380	
	CNC
	gague
MOQ	
/	+/- 0.01
T / T	50T / T;
	CNC
	20-25&NBSP T / T 50
1.Name	OEM
2.Process	CNC
3.	ADC12A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	accessoried
10.	AustrialEU
11&NBSP	ISO 9001
1	ISO10
2.	
3.surefacefinishment	kindlsavailable
	4
5.	
	6
7.	
&NBSP	
	ISO9001
OEM	