

Inspection Report



Report No.: XYK-140530
Supplier : XY-GLOBAL

Inspection Date: 26th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYK-140530 Item No.XY-144320	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-144320	80000PCS	1% inspection	0pcs	No failure	80000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

ชื่อ	บริษัท. จำกัดOEM
วัสดุ	ADC12A380
ผิว	ผิว
ขนาด	ขนาด
กระบวนการ	CNC
MOQ	MOQ
ราคา/ชิ้น	+/- 0.01
เวลา	T / T 50T / T ;
การรับประกัน	CNC
การชำระเงิน	การชำระเงิน
การขนส่ง	การขนส่ง
การบรรจุ	20-25T / T 50
การพิมพ์	การพิมพ์
1.Name	บริษัท. จำกัดOEM
2.Process	CNC
3.วัสดุ	ADC12A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.ขนาด	100
7.Specification	OEM
8.การชำระเงิน	25-30
9.การขนส่ง	accessoried
10.การบรรจุ	AustrialEU
11&NBSP	ISO 9001
การพิมพ์	
ISO	110
2.การชำระเงิน	
3.sureface	finishmentkindlsavailable
การบรรจุ	4
5.การชำระเงิน	
การบรรจุ	6
7.การชำระเงิน	
การพิมพ์	
การชำระเงิน	&NBSP
การบรรจุ	
การชำระเงิน	ISO9001
การบรรจุ	
OEM	