

Inspection Report

Report No.: 140422-01

Inspection Date: 22nd Apr 2014

Supplier :

Inspector: Ken Tung

Inspection only for: Item No. XY-21-85	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-21-85	800sets	100%	1 pcs	1pcs poor finish	800pcs

Appearance Inspection :

No failure,

1 pcs poor finish

Dimension Inspection:

No failure

Leakage Test:

No failure

Inspection Summary

The inspection sample plan are follow AQL . The result of inspection is acceptable.


Digital photo records :




1. Packing



2. Product




3. Product



4. Product



5. Product



6. Product



7 Product



8. Product



9. Mark



10. Carton

