

## Aluminum CNC Machining Parts



XY Electronics Technology Co., Ltd

## Inspection Report

Report No.: XYA-130820

Inspection Date: 15<sup>th</sup> Sep-, 2013

Supplier : XY-GLOBAL

Inspector: LEO

Inspection only for:	<u>Inspection Result:</u>
PO : XYA-130820    Item No.130020	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
130020	500PCS	3% inspection	0pcs	No failure	500pcs

### Appearance Inspection :

No failure,

### Dimension Inspection:

No failure , below measurement report for reference.

### Assembly Test:

No failure


### Inspection Summary

The inspection sample plan is 100% inspection.


### Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product: