

Части Алюминий ЧПУ Обрабатывающие



# XY Electronics Technology Co., Ltd

## Inspection Report

Report No.: XYA-130820  
Supplier : XY-GLOBAL

Inspection Date:15<sup>th</sup> Sep-, 2013  
Inspector:LEO

Inspection only for: PO . XYA-130820    Item No.130020	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
130020	500PCS	3% inspection	0pcs	No failure	500pcs

**Appearance Inspection :**

No failure,

**Dimension Inspection:**

No failure , below measurement report for reference.



**Assembly Test:**

No failure

**Inspection Summary**

The inspection sample plan is 100% inspection.

**Digital photo records :**

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product: