

Точности частей Аллюминиевые

Inspection Report

Report No.: XYA-130814
 Supplier : XY-GLOBAL

Inspection Date: 15th Sep-, 2013
 Inspector: LEO

Inspection only for: PO . XYA-130814 Item No.130353	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
130353	1000PCS	3% inspection	0pcs	No failure	1000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing	2. Product:
3. Product:	4. Product:
5. Product :	6. Product: